

**1. Q:** When I install Windows 8.1 in GPT mode, there is a water mark in the bottom right corner "Secure boot isn't configured correctly". How can I fix this?

**A:** Please enter BIOS\Security page to enable [Secure Boot] and choose Install Default Secure Boot Keys, then press [F10] to save settings and reboot the system.



**2. Q:** When I use the Sunlogin App to control my system via an Android system, there is an error message during remote desktop control. How do I solve this problem?

**A:** Please update to the latest Sunlogin PC client and App from the Sunlogin website:

<http://sunlogin.oray.com/en/download/>

**3. Q:** My DN2800MT system gets a distorted screen through the LVDS panel at Windows 7 boot screen. What should I do?

**A:** Since the vBIOS requires different settings for Windows 7, you might see such symptoms during booting.

Please flash the corresponding BIOS version for your system from our website:

<http://www.asrock.com/ipc/overview.asp?Model=DN2800MT&cat=Download&os=BIOS>